
4. Disconnect the power steering pipes and remove the steering gearbox mounting bolts.



CHANGED BY	
EFFECTIVE DATE	
AFFECTED VIN	